HOBBS®

MODEL 522-A PEANUT COMBINE PARTS CATALOG SUPPLEMENT

Contents

	PAGE
FRAME SECTION	5
COVER AND SHIELD SECTION	9
CLEANING SHOE SECTION	19
STRAW RACK SECTION	21
STEMMER SECTION	23
DRIVE SECTION, RIGHT SIDE	33

Note

The page numbers in this supplement correspond with those in the parts catalog.

July 30, 1976



FRAME SECTION

No.	Part No.	Description	No. Req'd	Replaces No.
5	9707	Frame, Middle Section, Left	1	9349
6	9708	Frame, Middle Section, Right	1	9350
7	9709	Frame, Rear Section, Right	1	9351
8	9710	Frame, Rear Section, Left	1	9352
27	2020	Nut, 5/8 UNC	1	--

NOTE: Parts 6310, 1011, 3059, 6312, 6315, 7019 and the 1/8 dia. x 5/8 long expansion pin have been deleted due to the updating process.



COVER AND SHIELD SECTION

No.	Part No.	Description	No. Req'd	Replaces No.
15	120300	Cover, Straw Rack Drive Side, Right	1	12873
16	120301	Cover, Straw Rack Drive Side, Left	1	12874
17	120296	Cover, Stripper Cylinder Side, Right	1	12869
18	120297	Cover, Stripper Cylinder Side, Left	1	12870
24	6054	Nut, Idler Adjusting	1	--
36	6670	Bracket, Belt Adjustor	1	new
37	120304	Deflector, Right	1	new
38	120305	Deflector, Left	1	new







CLEANING SHOE SECTION

No.	Part No.	Description	No. Req'd	Replaces No.
22	12849	Finger, Screening Size 80, Even	5	12848
24	6668	Pitman, Vibrating Screen Drive	1	6076 or 6667
45	120302	Plate, Material Guide, Right	1	12871
46	120303	Plate, Material Guide, Left	1	12872



STRAW RACK SECTION

No.	Part No.	Description	No. Req'd	Replaces No.
1	120306	Rack, Straw No. 2 & No. 4	2	12838
2	6662	Shaft, Straw Rack Rock, Rear	1	10105
3	6663	Shaft, Straw Rack Rock, Front	1	10106
7	2154	Sleeve, Rubber Bushing Insert 2" Long	2	1032
19	120307	Rack, Straw No. 1 & No. 3	2	12839
28	6666	Clamp, Rubber Bushing Retainer 1-3/4" wide	8	9418C
29	4044	Bushing, Rubber	4	--

NOTE: Parts 6172, 3058 and 3020 have been deleted because of the updating process.



STEMMER SECTION

No.	Part No.	Description	No. Req'd	Replaces No.
4	120213	Bottom, Stemmer (Virginia Peanuts)	1	--
-	120142	Bottom, Stemmer (Spanish Peanuts)	as req'd	--
-	12856	Bottom, Stemmer (For U.S.A.)	as req'd	--
22	6665	Pitman, Cleaning Shoe Drive, Right	1	6184 or 6671
26	6669	Arm, Cleaning Shoe Drive Pitman, Right	1	6048 or 6658 on right side only
28	5150	Saw, 72 Tooth Stemmer (For Va. Peanuts)	66	--
-	5150	Saw, 72 Tooth Stemmer (For Spanish Peanuts)	70	--
-	5150	Saw, 72 Tooth Stemmer (For U.S.A.)	74	--
30	2148	Spacer, Stemmer Saw (For Va. Peanuts)	70	--
-	2141	Spacer, Stemmer Saw (For Spanish Peanuts)	74	--
-	2076	Spacer, Stemmer Saw (For U.S.A. Optional)	78	--
36	2154	Sleeve, Rubber Bushing Insert, 2" long	1	1032



DRIVE SECTION, RIGHT SIDE

No.	Part No.	Description	No. Req'd	Replaces No.
16	5208	Idler, 6" Flat Belt	1	5207